


CONFIDENTIAL

Lih RD-122
T.O. I



8 April 1958



Dear 

Attached are two drawings that confirm our phone conversation regarding a change in the location of the connector cut-out for the Printer.

The receiver manufacturer has stated his acceptance of the connector placement as recommended by you, and has also expressed a desire that you furnish twelve correctly keyed connectors at your earliest convenience.

Yours truly,



Attachment:

Two drawings

MP
OC-E/R&D-EP/CEM:wlj
cc: R&D Subject File
R&D Chrono
EP Chrono

(8 April 1958)



DOC	65	REV DATE	20 MAR 1980	BY	064540
ORIG COMP	056	OPI	56	TYPE	01
ORIG CLASS	M	PAGES	2	REV CLASS	C
JUST	22	NEXT REV	2010	AUTH:	HR 78-2

(INC)

CONFIDENTIAL

